

88m  
6/9/05

	Type	L #	Hits	Search Text	DBs
1	BRS	L1	2	"5437938".pn.	USPAT; EPO; DERWEN T
2	BRS	L2	2	"5944144".pn.	USPAT; EPO; DERWEN T
3	BRS	L3	0	jp349893.fref.	USPAT; EPO; DERWEN T
4	BRS	L4	0	wo9818709.fref.	USPAT; EPO; DERWEN T
5	BRS	L5	0	ep035580.fref.	USPAT; EPO; DERWEN T
6	BRS	L6	0	ep935580.fref.	USPAT; EPO; DERWEN T
7	BRS	L7	0	ep0935580.fref.	USPAT; EPO; DERWEN T
8	BRS	L8	0	ep00935580.fref.	USPAT; EPO; DERWEN T
9	BRS	L9	0	ep000935580.fref.	USPAT; EPO; DERWEN T

14  
Backward  
Search

	Time Stamp	Comments	Error Definition	Errors
1	2005/06/09 13:43			
2	2005/06/09 14:31			
3	2005/06/09 14:31			
4	2005/06/09 14:33			
5	2005/06/09 14:32			
6	2005/06/09 14:32			
7	2005/06/09 14:32			
8	2005/06/09 14:32			
9	2005/06/09 14:32			

	Type	L #	Hits	Search Text	DBs
10	BRS	L10	2	"9818709" and elevator	USPAT; EPO; DERWEN T
11	BRS	L11	314	ito and elevator	USPAT; EPO; DERWEN T
12	BRS	L12	14027	"187"/\$.ccls.	USPAT; EPO; DERWEN T
13	BRS	L13	36	11 and 12	USPAT; EPO; DERWEN T
14	BRS	L14	1	"6012544".uref.	USPAT; EPO; DERWEN T
15	BRS	L15	2	"6012554".uref.	USPAT; EPO; DERWEN T
16	BRS	L16	8	"3211259".pn. "5429211".pn. "5469937".pn.	USPAT; EPO; DERWEN T
17	BRS	L17	14583	"187"/\$.ccls.	US- PGPUB; USPAT; EPO; DERWEN T

1/14

1/14

Forward Search

1/14  
Backward Search

	Time Stamp	Comments	Error Definition	Errors
10	2005/06/09 14:44			
11	2005/06/09 14:35			
12	2005/06/09 14:35			
13	2005/06/09 14:35			
14	2005/06/09 14:43			
15	2005/06/09 14:43			
16	2005/06/09 14:47			
17	2005/06/09 14:47			

	Type	L #	Hits	Search Text	DBs
18	BRS	L18	8138	(engine motor drive) near8 shaft near5 top	US- PGPUB; USPAT; EPO; DERWEN T
19	BRS	L19	60	17 and 18	US- PGPUB; USPAT; EPO; DERWEN T
20	BRS	L20	2021	(engine motor drive) near8 shaft near5 top	EPO; JPO; DERWEN T
21	BRS	L21	212678	elevator lift	EPO; JPO; DERWEN T
22	BRS	L22	112	20 and 21	EPO; JPO; DERWEN T

1 VA

1 VA

	Time Stamp	Comments	Error Definition	Errors
18	2005/06/09 15:05			
19	2005/06/09 15:04			
20	2005/06/09 15:05			
21	2005/06/09 15:05			
22	2005/06/09 15:05			